



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com

Risk Overview



1

Photo Captured: 07.19.2025

Damage / Overview:

Scope: Risk Overview

Component(s):

Description:

Address Verification



2

Photo Captured: 07.19.2025

Damage / Overview:

Scope: Address Verification

Component(s):

Description:



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com

Roof




3 Photo Captured: 07.19.2025

Damage / Overview:

Scope: Roof > Roof Details > Eave Depth

Component(s):

Description: Eave Depth



4 Photo Captured: 07.19.2025

Damage / Overview:

Scope: Roof > Roof Details > Shingle Gauge (Laminate)

Component(s): 30 year

Description: Shingle Gauge (Laminate) 30 year



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



5 Photo Captured: 07.19.2025

Damage / Overview:

Scope: Roof > Roof Details > Gutter

Component(s):

Description: Up to 5" Gutter



6 Photo Captured: 07.19.2025


Damage / Overview:

Scope: Roof > Roof Details > Pitch Gauge

Component(s):

Description: Pitch Gauge




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



7 Photo Captured: 07.19.2025

Damage / Overview:

Scope: Roof > Roof Details > Drip Edge

Component(s):

Description: Drip Edge



8 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Front

Component(s):

Description: Overview



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



9 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview



10 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview - Additional Facets



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



11 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview - Additional Facets



12 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview - Additional Facets



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



13 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview - Additional Facets




14 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview - Additional Facets



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview - Additional Facets

15 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s):

Description: Overview - Wind Overview

16 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Front

Component(s): Ridge Vent, Skylight

Description: Overview - Auxiliary Components Present : Ridge Vent and Skylight

17 Photo Captured: 07.19.2025



Damage / Overview: Overview


Scope: Roof > Slope > Front Slope
Front

Component(s): Ridge Vent, Skylight

Description: Overview - Auxiliary Components Present : Ridge Vent and Skylight

18 Photo Captured: 07.19.2025




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



19 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Front

Component(s): Skylight

Description: Overview - Auxiliary
Components Present : Skylight



20 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Front

Component(s): Skylight

Description: Overview - Auxiliary
Components Present : Skylight



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



21 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s): Skylight

Description: Overview - Auxiliary
Components Present : Skylight



22 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Front Slope
Slope
Front

Component(s): Ridge Vent

Description: Overview - Auxiliary
Components Present : Ridge Vent



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s):

Description: Overview

23 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s):

Description: Overview

24 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s):

Description: Overview - Wind
Overview

25 Photo Captured: 07.19.2025



Damage / Overview: Non Peril
Damage


Scope: Roof > Slope > Right Slope
Slope
Right

Component(s): Roof Covering

Description: Wear and Tear
present to Roof Covering

26 Photo Captured: 07.19.2025




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Non Peril Damage

Scope: Roof > Slope > Right Slope
Right

Component(s): Roof Covering

Description: Wear and Tear present to Roof Covering

27 Photo Captured: 07.19.2025



Damage / Overview: Non Peril Damage

Scope: Roof > Slope > Right Slope
Slope Right

Component(s): Roof Covering

Description: Wear and Tear present to Roof Covering

28 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



29 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s): Pipe Jack, Roof Vent(s)

Description: Overview - Auxiliary Components Present : Pipe Jack and Roof Vent(s)



30 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s): Pipe Jack

Description: Overview - Auxiliary Components Present : Pipe Jack



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s): Pipe Jack

Description: Overview - Auxiliary
Components Present : Pipe Jack

31 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s): Roof Vent(s)

Description: Overview - Auxiliary
Components Present : Roof Vent
(s)

32 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



33 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s):

Description: Overview - Additional Facets



34 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s):

Description: Overview - Additional Facets



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s):

Description: Overview - Additional
Facets

35 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Roof > Slope > Right Slope
Slope
Right

Component(s):

Description: Overview - Additional
Facets

36 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



37 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Back Slope
Slope
Back

Component(s):

Description: Overview



38 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Back Slope
Slope
Back

Component(s):

Description: Overview



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



39 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Back Slope
Back

Component(s):

Description: Overview - Wind
Overview



40 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Back Slope
Back

Component(s): Skylight

Description: Overview - Auxiliary
Components Present : Skylight

Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



41

Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Back Slope
Slope
Back

Component(s): Skylight

Description: Overview - Auxiliary
Components Present : Skylight



42

Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Back Slope
Slope
Back

Component(s): Skylight

Description: Overview - Auxiliary
Components Present : Skylight



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



43 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Slope
Left

Component(s):

Description: Overview



44 Photo Captured: 07.19.2025


Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Slope
Left

Component(s):

Description: Overview




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



45 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Slope
Left

Component(s):

Description: Overview - Wind
Overview



46 Photo Captured: 07.19.2025

Damage / Overview: Overview


Scope: Roof > Slope > Left Slope
Slope
Left

Component(s):

Description: Overview - Wind
Overview



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Left

Component(s): Pipe Jack, Roof Vent(s)

Description: Overview - Auxiliary Components Present : Pipe Jack and Roof Vent(s)

47 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Left

Component(s): Roof Vent(s)

Description: Overview - Auxiliary Components Present : Roof Vent (s)

48 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



49 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Slope
Left

Component(s): Pipe Jack, Roof Vent(s)

Description: Overview - Auxiliary Components Present : Pipe Jack and Roof Vent(s)



50 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Slope
Left

Component(s): Roof Vent(s)

Description: Overview - Auxiliary Components Present : Roof Vent (s)

Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



51

Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Left

Component(s):

Description: Overview - Additional Facets



52

Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Roof > Slope > Left Slope
Left

Component(s): Pipe Jack

Description: Overview - Auxiliary Components Present : Pipe Jack



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com

Elevation



53 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Elevation > Front Elevation

Component(s):

Description: Overview - Middle



54 Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Elevation > Front Elevation

Component(s):

Description: Overview - Left to Right



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Elevation > Front Elevation

Component(s):

Description: Overview - Right to Left

55 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Elevation > Right Elevation

Component(s):

Description: Overview - Left to Right

56 Photo Captured: 07.19.2025

PHOTO SHEET

Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



57

Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Elevation > Right Elevation

Component(s):

Description: Overview - Middle



58

Photo Captured: 07.19.2025

Damage / Overview: Overview

Scope: Elevation > Right Elevation

Component(s):

Description: Overview - Right to Left



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Elevation > Back Elevation

Component(s):

Description: Overview - Left to Right

59 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Elevation > Back Elevation

Component(s):

Description: Overview - Middle

60 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Elevation > Back Elevation

Component(s):

Description: Overview - Right to Left

61 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Elevation > Left Elevation

Component(s):

Description: Overview - Left to Right

62 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Elevation > Left Elevation

Component(s):

Description: Overview - Middle

63 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Elevation > Left Elevation

Component(s):

Description: Overview - Right to Left

64 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com

Interior



Damage / Overview: Overview

Scope: Interior Room
Enclosed patio

Component(s):

Description: Overview

65 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Interior Room
Enclosed patio

Component(s):

Description: Overview

66 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Interior Room
Enclosed patio

Component(s):

Description: Overview

67 Photo Captured: 07.19.2025



Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:

68 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:

69 Photo Captured: 07.19.2025



Damage / Overview:


Scope: Interior Room
Enclosed patio

Component(s):

Description:

70 Photo Captured: 07.19.2025




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:

71 Photo Captured: 07.19.2025



Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:

72 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:

73 Photo Captured: 07.19.2025



Damage / Overview: Non Peril
Damage

Scope: Interior Room
Enclosed patio

Component(s):

Description:

74 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:

75 Photo Captured: 07.19.2025



Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:

76 Photo Captured: 07.19.2025

PHOTO SHEET



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



77

Photo Captured: 07.19.2025

Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:



78

Photo Captured: 07.19.2025

Damage / Overview:

Scope: Interior Room
Enclosed patio

Component(s):

Description:



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: No Damage

Scope: Interior > Walls Room
Enclosed patio

Component(s):

Description: No Damage

79 Photo Captured: 07.19.2025



Damage / Overview: No Damage

Scope: Interior > Walls Room
Enclosed patio

Component(s):

Description: No Damage

80 Photo Captured: 07.19.2025

Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



81

Photo Captured: 07.19.2025

Damage / Overview: No Damage

Scope: Interior > Walls Room
Enclosed patio

Component(s):

Description: No Damage



82

Photo Captured: 07.19.2025

Damage / Overview: No Damage

Scope: Interior > Walls Room
Enclosed patio

Component(s):

Description: No Damage



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: No Damage

Scope: Interior > Walls Room
Enclosed patio

Component(s):

Description: No Damage

83 Photo Captured: 07.19.2025



Damage / Overview: No Damage

Scope: Interior > Walls Room
Enclosed patio

Component(s):

Description: No Damage

84 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview:

Scope: Interior

Component(s):

Description:

85 Photo Captured: 07.19.2025

Other Structure



Damage / Overview: Overview

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview

86 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage

87 Photo Captured: 07.19.2025



Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear

88 Photo Captured: 07.19.2025

PHOTO SHEET



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



89

Photo Captured: 07.19.2025

Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear



90

Photo Captured: 07.19.2025


Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear

91 Photo Captured: 07.19.2025



Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear

92 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



93 Photo Captured: 07.19.2025

Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear



94 Photo Captured: 07.19.2025

Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview

95 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview

96 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview

97 Photo Captured: 07.19.2025



Damage / Overview: Overview


Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview

98 Photo Captured: 07.19.2025




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Overview

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview

99 Photo Captured: 07.19.2025



Damage / Overview: Overview

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview

100 Photo Captured: 07.19.2025



Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



101

Photo Captured: 07.19.2025

Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear



102

Photo Captured: 07.19.2025


Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



103

Photo Captured: 07.19.2025

Damage / Overview: Non Peril Damage

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Non Peril Damage - Wear and Tear



104

Photo Captured: 07.19.2025


Damage / Overview: Overview

Scope: Other Structure > Storage Shed

Component(s): Pre-Built Storage Shed

Description: Overview




Phone: (800) 416-1773 Fax: (512) 688-5220
www.bcc-ltd.com



Damage / Overview: Non Peril
Damage

Scope: Other Structure > Storage
Shed

Component(s): Pre-Built Storage
Shed

Description: Non Peril Damage -
Wear and Tear

105

Photo Captured: 07.19.2025